



• DRAINAGE ISSUES MANY DRAINS ARE FREQUENTLY CLOGGED. COUPLE OF PROPERTIES WITH FLOODING ISSUES.

• SEWER ISSUES

COUPLE OF PROPERTIES WITH SEWER SERVICE ISSUES.

PEDESTRIAN ISSUES

TYPE OF CONCRETE VARIES CONSIDERABLY; SIDEWALKS ARE UNEVEN.

DRIVING ISSUES

ROADWAY IS IN TERRIBLE CONDITION.

TOO MANY POTHOLES.

DRIVERS OFTEN USE GROZIER RD AS A CUT THROUGH.

BACKING ONTO STREET DIFFICULT IN WINTER.

DRIVERS CONCERNED ABOUT NARROWING STREETS.

• CYCLING ISSUES

POTHOLES MAKE CYCLING VERY DIFFICULT.

• MISCELLANEOUS ISSUES

MANY OF THE UTILITY POLES ARE LEANING AND **OUT OF ALIGNMENT.**


CONCERNED WITH MAINTENANCE REQUIREMENTS OF PLANTING STRIP AND UNIFORMITY OF SIDEWALK APPEARANCE IF SOME RESIDENTS DO NOT WANT STRIPS.

CONCERNED WITH EXTENTS OF TREE PRUNING.

GLOBAL COMPLIMENTS

• CYCLING COMPLIMENTS

BIKE LANES ON HURON AVE ARE A BIG IMPROVEMENT.



HURON A PROJECT AREA GROZIER ROAD

COMMENTS INCLUDED OM THIS FIGURE ARE FROM SURVEY RESPONSES AND COMMUNITY MEETING INPUT THROUGH 03.01.11





